

Summary of Amendment to Assessment Application Report

The table below summarises updates included in this Assessment Application Report to:

- reflect changes made to deviated well trajectory names (refer to summary below);
- correct a minor error identified in relation to well numbers;
- provide additional details regarding the well path lengths and depths; and
- correct some minor errors in relation to disturbance calculations and percentage calculations.

Section of Report	Details of Update
Chapter 2	<ul style="list-style-type: none"> • Table 2-1 (page 15) updated to correct rounding error in total disturbance to PAA and SCA (both were 35.83 ha and both are now 35.84 ha) • Figure 2-1 (page 17) updated to reflect revised well path names.
Chapter 4	<p>Table 4-3 updated to correct:</p> <ul style="list-style-type: none"> • surface disturbance during construction on 1DY931 was incorrectly shown as 3.79 ha and now correctly shown as 3.74 ha (page 48); • total surface disturbance during construction was incorrectly shown as 24.98 ha and now correctly shown as 25 ha (page 51); • total surface impact during operations was incorrectly shown as 1.47 ha and now correctly shown as 1.4 ha (page 51); and • Corrected figure of 35.83 ha to 35.84 ha (page 54)
Chapter 5	<p>Table 5-1 (page 65) updated to correct:</p> <ul style="list-style-type: none"> • surface disturbance during construction on 1DY787 was incorrectly shown as 0.11 ha and now correctly shown as 6.77 ha; • surface impact during operations on 1DY787 was incorrectly shown as 0.00 ha and now correctly shown as 1.13 ha; • % impact on SCL construction on 1DY787 was incorrectly shown as 0.04% and now correctly shown as 2.54%; • % impact on SCL during operations on 1DY787 was incorrectly shown as 0.00% and now correctly shown as 0.40% • total surface disturbance during construction was incorrectly shown as 34.93 ha and now correctly shown as 35.84 ha; • total surface impact during operations was incorrectly shown as 1.09 ha and now correctly shown as 2.21 ha; • % impact on SCL construction was incorrectly shown as 1.66% and now correctly shown as 1.7%; and • % impact on SCL during operations was incorrectly shown as 0.05% and now correctly shown as 0.10%.
Chapter 10	Corrected figure of 35.83 ha to 35.84 ha (page 80)
Appendix 3	Property 1 Figure in Appendix 3 (page 235) updated to provide details of deviated well trajectory lengths and depths.

Section of Report	Details of Update
	<p>Property 2 Figures in Appendix 3 (page 239 and 240) updated to reflect revised deviated well trajectory names. Details of deviated well trajectory lengths and depths added.</p> <p>Property 2 infrastructure summary in Appendix 3 (page 248) updated to correct the description of well trajectory numbers:</p> <ul style="list-style-type: none"> • Dot point '2 x additional subterranean deviated well trajectories' removed. • Dot point '14 x subterranean deviated well trajectories' updated to describe these as 14 x <u>additional</u> subterranean deviated well trajectories'.

The following changes have been made to the deviated well trajectory names on Property 2:

- Lot 2RP99387
 - Longswamp 331 changed to Longswamp 332
- Lot 1DY787
 - Longswamp 311 changed to Longswamp 314
 - Longswamp 314 changed to Longswamp 311
 - Longswamp 372 changed to Longswamp 371
- Lot 2DY787
 - Longswamp 206 changed to Longswamp 207